

From: [Michael PINTO](#)
To: [Bury, Carolyn](#)
Subject: RE: Letters
Date: Friday, November 22, 2013 9:25:46 AM

CRA does not think it's a weep hole, but they do believe it is surface water that is draining based on the height of the hold. Maybe something hit the wall. They will take a look it ASAP and if necessary arrange for a repair.

Michael Pinto
RETIA USA LLC/Legacy Site Services LLC
468 Thomas Jones Way, Suite 150
Exton, PA 19341
Office: 610 594-4435
Fax: 610 594-4439



From: Bury, Carolyn [<mailto:bury.carolyn@epa.gov>]
Sent: Friday, November 22, 2013 9:57 AM
To: Michael PINTO
Subject: RE: Letters

Hi Mike,

I'll just send you a letter asking that the monitoring be continued.

Say, when you get a chance in the next few weeks, could you please send me a brief synopsis of the property ownership since Pennwalt Corporation (AOC), including the entire formal name of each company, which I need for the Statement of Basis? You know, I can't recall what the exact relationship is between Legacy Site Services and Arkema - are you contracted to Arkema or an arm of Arkema? At one time I looked up Arkema and found that the company is headquartered in Lyon, France, and is a French-owned company. Is that correct?

Also, please confirm that the photo of the seawall, attached, shows a weephole drilled for storm water management. I think that the vegetation hanging down suggests that the top of the wall may be two or so feet from the hole.

Thanks!

Carolyn

From: Michael PINTO [<mailto:michael.pinto@total.com>]
Sent: Friday, November 22, 2013 8:11 AM
To: Bury, Carolyn

Subject: Letters

Carolyn,

I did find your letter and our response. Pete Swanson at CRA recalls that we discussed the results of the 2010 sampling with you and we concluded that additional sampling could be deferred until the CMS was approved and the long term monitoring plan was implemented. This was predicated on the CMS being approved shortly after our conversation. I don't remember any of this and CRAs recollection doesn't quite make sense to me. Either way, if you prefer we can send you a letter stating that we will resume sampling as requested in your 2010 letter and propose a schedule and report format, or you can send us a letter describing what you want.

Michael Pinto
RETIA USA LLC/Legacy Site Services LLC
468 Thomas Jones Way, Suite 150
Exton, PA 19341
Office: 610 594-4435
Fax: 610 594-4439

